


Sonuç

Ölçme tarihi 18.09.2024 02:26:44
Yer
Pozisyon , Sol
Kullanıcı İbrahim
Ölçüm cihazı 523090282
Hedef profil 60_E2



Kenar Aşınması




#	Açı (°)	Tamir öncesi Δ (mm)	Tamir sonrası Δ (mm)
1	-85,0	-0,0	0,0
2	-80,0	0,1	0,0
3	-75,0	0,1	-0,0
4	-70,0	-0,0	-0,1
5	-65,0	-0,0	-0,1
6	-60,0	-0,3	-0,3
7	-55,0	-0,4	-0,4
8	-50,0	-0,3	-0,5
9	-45,0	-0,4	-0,5
10	-40,0	-0,3	-0,4
11	-35,0	-0,2	-0,3
12	-30,0	-0,0	-0,1
13	-24,9	0,1	-0,0
14	-20,0	0,2	0,1
15	-15,0	0,3	0,1
16	-10,0	0,2	-0,0
17	-5,0	0,2	0,1
18	0,0	0,1	0,1
19	5,0	-0,2	-0,1

Tarih: _____ İmza | Pul: _____

Sonuç

Ölçme tarihi 18.09.2024 02:26:44
Yer
Pozisyon , Sol
Kullanıcı İbrahim
Ölçüm cihazı 523090282
Hedef profil 60_E2



Pozisyon	Tamir öncesi Δ (mm)	Tamir sonrası Δ (mm)
X-35	0,1	0,2
X-30	0,3	0,4
X-25	0,2	0,1
X0	0,1	0,1
X+5	0,0	0,1
X+14	0,2	0,1
Y-14	0,0	0,0


Tarih: _____ İmza | Pul: _____

Sonuç


Ölçme tarihi 18.09.2024 02:26:44
Yer
Pozisyon , Sol
Kullanıcı İbrahim
Ölçüm cihazı 523090282
Hedef profil 60_E2



Metal Kaldırma



Metal Kaldırma



Tarih: _____ İmza | Pul: _____